Selection and Ordering data	Order No.	
FAT & Factory Certificates for extractive gas analyzers Series 6 and ULTRAMAT 23	7 M B 8 1 0 0 -	not applicable for
Factory acceptance test (with customer)		
Visual inspection and basic adjustments		
Without	0	
Visual acceptance Visual acceptance, function, calibration zero and span	1 2	
·		
<u>Measuring response</u> Without	A	
Signal noise, drift	B	
Signal noise, drift, linearity, T ₉₀ time	С	
Compensation, cross interference	_	
Without	A	
Pressure compensation	B C	FIDAMAT
1 interferent component 2-3 interferent components	D	
Pressure compensation and 1 interferent component	Ĕ	FIDAMAT
Pressure compensation and 2-3 interferent components	F	FIDAMAT
Ex protection	_	
Without	0	
Pressurized enclosure Ex units (functionality)	1	
Relays		
Without	0	10" real coreien
Relay test	1	19" rack version
Certificates		
General certificates Quality inspection certificate to DIN EN 10204 2.1 1)	0	
Adjustment certificate (with test gas)	1	
Certificate of origin 1)	2	
Certificate of origin and adjustment certificate	3	
Certificate of origin and quality inspection certificate 2.1 EN 10204 1)	4	
Certificate of origin, adjustment certificate and quality inspection 2.1 EN 10204	5	
Factory inspection certificate to DIN EN 10204 2.3		
Without	A	
Signal noise, drift, linearity Signal noise, drift, linearity, pressure compensation	B C	FIDAMAT
Signal noise, drift, linearity, pressure compensation	D	FIDAMAT
Factory inspection certificate to DIN EN 10204 2.3, extended		
Without	A	
Cross interference (H ₂ O and 2 additional gases)	В	
T ₉₀ time	C	
Influence of CO ₂ containing atmosphere Cross interference ²⁾ and T ₉₀ time		
Cross interference ² and r ₉₀ time Cross interference ²⁾ and influence of CO ₂ containing atmosphere	E F	
T ₉₀ time and influence of CO ₂ containing atmosphere	G	
Cross interference 2), T ₉₀ time and CO ₂ influence of CO ₂ containing atmosphere	Ĥ	
Factory inspection certificate to DIN EN 10204 2.3, language		
German	0	
English French	1 2	
Necessary analyzer information	Order code	
Please add "-Z" to Order No. and specify order code.	2.30.0000	
Information about product / order with item no. and contact person	Y22	
(VReg, Region or Distributor)		
1) Can be ordered also after delivery.		
2) H ₂ O and 2 additional gases.		